

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

FS861
North
> 1
1.166 mi.
6154 ft.

X
2059 WEST 12TH ST
BROOKLYN, NY
Site 2 of 2 in cluster FS

NY Spills S106008652
N/A

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: X
Address: 2059 WEST 12TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0207616 / 2006-03-24
Facility ID: 0207616
Facility Type: ER
DER Facility ID: 69242
Site ID: 73578
DEC Region: 2
Spill Cause: Human Error
Spill Class: C3
SWIS: 2401
Spill Date: 2002-10-23
Investigator: rmpiper
Referred To: Not reported
Reported to Dept: 2002-10-23
CID: 205
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-10-23
Spill Record Last Update: 2006-03-24
Spiller Name: RONALD PALMESE
Spiller Company: COLUMBIA UTILITIES
Spiller Address: 1350 60TH ST
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 1/7/04-Vought-Spill transferred from Vought to Austin. 01/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 12/16/05- DEC Piper left message for Renzo Rossi, homeowner of misdelivery, requesting callback. 3/24/06- DEC Piper visited site. Renzo is not owner of time of spill. New owner let Piper inspect. No signs of oil contamination. Cleaned to owners specs. Closed."
Remarks: "DRIVER PUMPED INTO A HOUSE WITH NO TANK HOOKED UP."

All Materials:

Site ID: 73578
Operable Unit ID: 860424
Operable Unit: 01
Material ID: 518192
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 8.00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered: .00
Oxygenate: Not reported